



How to build a diesel injector pop tester



Design Considerations

Bottle Jack vs. Grease Gun

Gauge Sizing

-
-
-





Last edited by cornblatt; 06-07-2008 at 01:42 PM. Reason: Added info




#2
06-06-2008, 06:38 PM



Part 2 of 2

**Fill pinhole with JB Weld (both sides).
Clean threads before it dries.**





Fluid supply fitting JB Welded to jack reservoir


Pinhole filled (JB Weld)

Threaded bushing welded to jack nut

Hole plugged with screw, sealed inside with JB Weld

Holes drilled for mounting





- A Jet pattern closed and well atomized
- B Jet pattern torn up, too wide and spreading

3 Test jet: During short, fast partial strokes (at least 2 strokes per second) the jet should be rather closed and tear off well.



